



NOTES:

1. CONTRACTOR SHALL MAKE "COMPLETE CONNECTION" IN GOOD WORKING ORDER AND SHALL PROVIDE ALL NECESSARY FITTINGS, COUPLING ETC. AS MAY BE REQUIRED.
2. 12 GAUGE SOLID COPPER INSULATED TRACER WIRE SHALL BE SECURED TO POLYETHYLENE PIPE. LEAVE 3' NEATLY COILED IN METER BOX.

WATER METER
DETAIL
 NO SCALE

